

State of Utah department of natural resources division of oil, gas and mining

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 801-538-5340

0024

August 1, 1988

T0:

John Whitehead, Permit Supervisor

FROM:

Richard V. Smith, Geologist RVS

RE:

Review of NOV-88-20-1-1 Informal Abatement Response, Co-Op Mining Company, Bear Canyon Mine, ACT/015/025, Folder #2,

Emery County, Utah

The operator apparently informally submitted materials as an abatement response to NOV-88-20-1-1. Water monitoring stations identified, in response materials, as SBC-8 and SBC-7 do not agree with stations designated SBC-8 and SBC-7 in the recompiled PAP. Underground water survey data are shown on mining sequence illustrations (Plates 3-4 and 3-4a).

Recommendations

- 1. Request the operator to formally submit the abatement response.
- 2. Request the operator to correct the discrepancy in the locations of stations SBC-8 and SBC-7.
- 3. Direct that mining sequence illustrations showing underground water survey information be revised to be incorporated into the Hydrology Chapter as Plates with seven series numbers.

djh

cc: P. Grubaugh-Littig

T. Munson

9206R/43